

Roofing:

- Use of 0.5mm thick pre-painted longspan corrugated roofing sheets;
- Use of J-bolts (6mm dia) as fastener along the edges;
- Installation of angle bars at both ends of the roof.



Purlins:

- Replacement of wood with steel purlins (whenever possible);
- Placed more densely at both ends.



Trusses:

 Either partial or complete replacement depending on its condition and existing materials used;

 For totally damaged trusses: total replacement with steel truss is

recommended.





Common damages:



Common damages:



Damage to ceiling

Common damages:



Damage to ceiling

Ceiling:

Wooden ceiling joists;

- Marine plywood (1/4") both for interior

and exterior.





Windows:

- Jalousie windows with clear glass blades;
- JaloPlus-type frame;
- Fixed clear glass transoms on wood jambs.




Doors:

- Panel Type door (swing-out);
- Lever-type lockset;
- Fixed glass
 transom on
 wooden
 jambs/frame.



Lighting and Fixtures:

- 4/6 sets of
 1-40watts
 Industrial
 Type
 fluorescent
 lamp;
- 2/4 sets of duplex convenience outlets.



Chalkboard:

- panoramic chalkboard measuring 4.88m length by 1.22m width framed w/ thickness of 13 cm at center and 42cm at the











PWD ramp:

- Whenever applicable, will be constructed as required under BP 344.













Kagawaran ng Edukaspon

AIDE MEMOIRE

25 May 2021

UPGRADING OF SCHOOL BUILDING DESIGNS
TO CONFORM WITH THE CHANGING ENVIRONMENT AND BUILDING REQUIREMENTS OF SCHOOLS

The Philippines belongs to the Pacific Ring of fire where many earthquakes and volcanic eruptions occur. Moreover, its geographic location along the West Pacific—considered the world's busiest typhoon belt—makes it prone to tropical cyclones or typhoons, or an average of 20 typhoons experienced yearly. To date, earthquakes, volcanic eruptions, and typhoons have become more frequent and with greater magnitude and intensity.

I. Rationale

In the inventory records of school facilities in all public elementary and secondary in the inventory records of school facilities in all public elementary and secondary schools nationwide, various school building types exist from as early as 1900. Most of these were built over 25 years ago, and many are more than 40 years old. Needless to say, these old structures, particularly those constructed from 1901 to 1994, no longer conform to the latest Philippine building codes and laws (National Building Code, Architectural Code, Fire Code, Accessibility Law, and the National Structural Code).

Under the said codes, School Buildings or School Facilities are classified as "Essential Structures"—the same category as Hospitals—which are necessary for response and recovery during times of emergencies and disasters. A sad reality, and contrary to the mandate of ensuring learning continuity, school buildings and facilities are often used as evacuation centers or some other purpose.

Inspection of school structures show different school building designs, adapted to the culture, time period, and response to changing climate and new requirement Designs also vary depending on fund source—LGU, private donations, Oversess Development Assistance (ODA) projects, or the national government, through





Office of the Undersecretary for Administration (OUA)

Chine of Page 185, Indicated and Communications Technology Service 18-20 Disaster Risk Reduction and Management Service (BASS), Bareau of Learner Support Service 1850, Bayes and Control Service 1850 Disaster Risk Reduction and Management Service (BASS), Bayes and Service (SSSO) Service 1850, Central Security & Service (SSSO) Department of Education, Central Office, Meral Service, 18-20, Service 1850, Page 1850, Pa

into by the different stakeholders in determining the necessary assistance that



Standard Fence for Schools

e. Elevation of School Buildings

In the conduct of assessment of schools, engineers should be aware of the flood history of the school so that necessary site adaptation can be made such as elevating the school building at least one (1) meter higher that the flood history level or the construction of school buildings on stilts.

The devastations caused by the massive flooding in 2020 in the provinces of Cagayan and Isabela in the Cagayan Region led the Office of the Undersecretary for Administration (OUA) to construct a flood marker in all affected schools to serve as guide for engineers in evaluating the requirements of the school.

Standard Design of Flood Marker








Aide Memoire dated May 25, 2021

Flood Marker:

- To be installed in flood prone schools;
- Alert/awareness in times of flooding;
- Provide info during validation of engineers for the construction of new buildings.
















DepED STANDARD COLOR SCHEME

